


# Punch Down Tool




STEP 1  
Place UTP/STP cable on tool




STEP 2  
Stripping Round Cable



STEP 3  
Stripper UTP/STP Jacket



STEP 4



STEP 5  
Punch down (RP-PD318)